Weathertzatton Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/15015SE-3111/1
Work Order Type: Weatherization

Audit Name: 15015SE-3111Audit (7)

CLIENT INFORMATION

Client Name: Address:

Client ID: 15015SE-3111 Whitwell, TN 37397

Alt. Client ID: Marion

<u>AGENCY INFORMATION</u>

Agency: Southeast Tennessee Resource Agency **Agency Phone:** 423-9492 x191

Address: 312 Resource Rd **Fax:** (423) 949-4023

Dunlap, TN 37327 Email Address:

Agency Contact: Self, Philip Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	

Contractor's Signature:

COMMENT

1970's site built home.

Measures

1	Measure 1 Install pressure relief piping				Componen	ts			Inspected
C	omment 8' of 1"	diameter pressure relief	piping						
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	Install 8' of pressure relief piping to the outside of the house.	Each	1					
C	Other Detail								
				Measure	e Sub Total:] ;	Sub Total:	
	Field Notes:								
	Measure 2 Floo	or Ins. R-19			Componen Estimated			Actual	Inspected
C		or Ins. R-19 Description / Comment	Units	Qty	•		Qty		Inspected Total
C	omment		<i>Units</i> SqFt		Estimated		Qty	Actual	
C #	omment Material / Labor	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
C #	omment Material / Labor Insulation	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
C #	omment Material / Labor Insulation	Description / Comment Floor Insulation -		Qty	Estimated		Qty	Actual	
C # 1	omment Material / Labor Insulation	Description / Comment Floor Insulation -	SqFt	Qty 1306	Estimated			Actual	

	Measure 3 DWI	H Pipe Insulation			Componen	its			Inspected
C	comment 10' of 1	" insulation wrap.							
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Pipe Insulation	Each	1					
3	Other	DHW Pipe Insulation	Each	1					
C	Other Detail								
				Measur	e Sub Total:		,	Sub Total:	
	Manager A. Attic	- Inc. D 20							Inspected
		Ins. R-30			Componen	its All		,	Inspected
C	Comment				Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1306					
C	Other Detail						1		
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

		Estimated						
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	CO monitor	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
Labor	Labor	Each	1					
Other Detail								
Field Notes:			Measure	e Sub Total:			Sub Total:	
Measure 6 Repl	ace Gas stove			e Sub Total:	ts			Inspecte
	lace Gas stove							Inspecte
Measure 6 Repl	lace Gas stove Description / Comment	Units		Componen		Qty	ı	Inspecte
Measure 6 Repl Comment Material / Labor	Description / Comment Replace a GEXL44 4 burner with oven gas			Componen <i>Estimated</i>	1		Actual	
Measure 6 Repl Comment Material / Labor Unspecified	Description / Comment Replace a GEXL44 4	Units	Qty	Componen <i>Estimated</i>	1		Actual	
Measure 6 Repl Comment Material / Labor Unspecified	Description / Comment Replace a GEXL44 4 burner with oven gas	Units	Qty	Componen <i>Estimated</i>	1		Actual	
Measure 6 Repl Comment : Material / Labor	Description / Comment Replace a GEXL44 4 burner with oven gas	Units	Qty	Componen <i>Estimated</i>	1		Actual	

<u>-</u>	or Barrier Needed ement/CrawIspace)			Componen	ts			Inspected
walls an earth. M	6 mil poly. Must be insta d support piers. Must be ust be secured at all sea rization Materials and So	securely ms. Refe	fastene r to Atta	ed. Must be achment A-S	cleated c	lown to		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Basement /Crawlspace Vapor Barrier	SqFt	1436					
2 Labor	Labor	Each	1436					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
		Work O	rder Grai	nd Total:		Gran	d Total:	